

**TOYOTA****HIEWA AUTO GALLERY (LARKIN) SDN BHD**

(1254591-P)

Page: 1

Service Center : No. 9, Jalan Gagah, Larkin Industrial Estate, 80350 Johor Bahru.

and Body & Paint Tel: 07-2376770, 07-2353451 (Service) Fax: 07-2376729

Tel: 07-2376825, 07-2377195 (Body & Paint)

Sales Center : No. 31, Jalan Tun Abdul Razak, Susur 5, 80000 Johor Bahru.

Owner's Name and Address Tel: 07-2210600, 07-2248397, 07-2242905 Fax: 07-2230596 Date: 11/10/2023

PERBADANAN PRODUKTIVITI MALAYSIA (M)
PEJABAT WILAYAH SELATAN, NO.8
JALAN PADI MAHSURI
BANDAR BARU UDA
81200

TGN51R-NKPSKEFJ
8MD8778
PN111NV5107009923
2TR7526721
SILVER METALLIC

No : 3320150164

Quotation Valid for 14 days

31/05/2013

HIEWA AUTO GALLERY LARKIN
9, JALAN GAGAH
LARKIN INDUSTRIAL ESTATE
80350 JOHOR BAHRU, JOHOR
332 Tel No: 072376770

CUSTOMER REQUEST	JOB DESCRIPTION	LABOUR	QTY	LIST PRICE	SPARE PARTS		NET PRICE
					Disc	%	
1.110K SVC							
2.WASH+BACTAKLEEN 3.WAB	MXT03 MAXCHECK ADVANCE			136.50			
4.REPLACE BRAKE SHOE	TN90915YZZD2 OIL FILTER ELEMENT		1	38.60	05		36.67
5.REPLACE BATTERY	08808003L WINDOW WASHER 30ML		1	3.00	05		2.85
6.REPLACE ALL THE WIPER	0887703471MA NOVIRUCLEAN 3471		1	12.11	05		11.50
7.REPLACE REMOTE BATTERY	THFSNCF5W401L FULLY SYN TM 5W40 1L		2	67.00	05		127.30
(STIKER OREN)8.REPLACE	0881380019 PETROL INJ CLEANER		2	57.00	05		108.30
BOTH TAILGATE 9.GREASING	THFSNCF5W404L FULLY SYN TM 5W40 4L		1	259.00	05		246.05
PROPELER SHAFT 10.TO	8713906080 ELEMENT AIR REFINER		1	77.00	05		73.15
PERFROM AC SVC PACKAGE-I	9043012031 GASKET		1	2.80	05		2.66
	MZ2010 REPLACE BATTERY			6.50			
	28800YZZLH BATTERY-55D23L W/H		1	373.00	05		354.35
	88399 OTHERS - AIR-CONDITIONER			396.50			
	4459100080 DRYER		1	42.00	05		39.90
	MZ4025 DISINFECTION (BACTAKLEEN)			19.50			
	0887780040MA BACTAKLEAN VILTRAMIS		1	36.33	05		34.51
	83299 OTHERS - SWITCH - REGULATOR			130.00			
	689600K251 STAY BACK DOOR LH		1	60.00	05		57.00
	689500K251 STAY BACK DOOR RH		1	60.00	05		57.00
	D05002 DIAG-BODY EXT - DIRT,STAIN, DISCOLORATI			26.00			

**TOYOTA**

REPAIR ESTIMATE

HIEWA AUTO GALLERY (LARKIN) SDN. BHD. (1254591-P)

Page: 2

Service Center : No. 9, Jalan Gagah, Larkin Industrial Estate, 80350 Johor Bahru.

and Body & Paint Tel: 07-2376770, 07-2353451(Service) Fax: 07-2376729

Tel: 07-2376825, 07-2377195 (Body & Paint)

Owner's Name and Address Sales Center : No. 31, Jalan Tun Abdul Razak, Susur 5, 80900 Johor Bahru.

PERBADANAN PRODUKTIVITI MALAYSIA Tel: 07-2210600, 07-2248397, 07-2242805 Fax: 07-2230596

Date : 11/10/2023

PEJABAT WILAYAH SELATAN, NO.8

BMD8778

No : 3320150164

JALAN PADI MAHSURI

PN111NV5107009923

BANDAR BARU UDA

2TR7526721

Quotation Valid for 14 days

81200

SILVER METALLIC

31/05/2013

HIEWA AUTO GALLERY LARKIN
9, JALAN GAGAH
LARKIN INDUSTRIAL ESTATE
80350 JOHOR BAHRU, JOHOR
332 Tel No: 072376770

CUSTOMER REQUEST	JOB DESCRIPTION	LABOUR	QTY	LIST PRICE	SPARE PARTS		NET PRICE
					Disc	%	
MZ8017	4 WHEELS ALIGNMENT & 4 WHEELS BALANCING	91.00					
75299	OTHERS - MIRROR VISOR	32.50					
852420K010	BLADE REAR WIPER		1	30.70	05		29.17
852140D070LP	WIPER RUBBER RH-1877		1	20.00	05		19.00
8521406030LP	RUBBER WIPER LH-878		1	8.60	05		8.17
D09001	DIAGNOSIS - OTHERS	45.50					
MZ2035	PETROL ENGINE FLUSH ADDITIVE	13.00					
0881480061	PETROL E/G FLUSH ADT		1	48.00	05		45.60
MZ2002	REPLACE BRAKE SHOE	58.50					
044950K120	BRAKE SHOE KIT REAR		1	453.00	05		430.35
D06002	DIAG-BODY INT - DIRT, STAIN, DISCOLORATI	26.00					

TOTAL AMOUNT(EXCLUDING TAX)

2,665.03

SERVICE TAX @ 6%

53.04

TOTAL AMOUNT PAYABLE(INCLUSIVE OF TAX)

2,718.07

All parts supplied are new excluding Fuel Injection Pump & Injector, and Alternator which are reconditioned. T&C apply.

For all warranty related inquiries, please refer to the Toyota Careplus Service Booklet or visit Toyota Malaysia official website