


**GAMBAR2 KEROSAKAN
TANDAS2 DI BLOK INOVASI
2hb Jun 2022 – Kenalpasti Masalah (Kontraktor)**



Gambar Diatas : Dinding basah - air mengalir dari dalam siling (tandas lelaki tgkt bawah)



Gambar Diatas : Soket paip bocor (tandas lelaki tgkt bawah)



Gambar Diatas : Soket paip bocor - tandas lelaki tgkt 1 (ICC)



Gambar Diatas : Soket paip bocor - tandas wanita tgkt 1 (ICC)



Gambar Diatas : Tray out sinki rosak - tandas L tgkt 2 (Inovasi)