

Kebocoran Siling di 2 lokasi
Dalam bilik Gym lama & di laluan Dewan (Depan bilik Gym)
Blok Produktiviti



Gambar Atas : Bilik Gym Lama



Gambar Atas : Punca - Salur Aircond bocor (Anak panah)



Gambar diatas (dalam bulatan) : Punca salur aircond - Daripada bilik AVA (dewan)



Gambar Atas : Laluan Dewan (depan bilik Gym Lama)



Gambar Atas : Punca – Kebocoran bumbung (depan bilik AV)